

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

UNIT 1	YPE: (check a	ll that apply	to tl	his audit i	with s	ame Per	mit number)	
Lined MSWLF	LCID	YW	X	Transfer	X	Compost	SLAS	COUNTY: Yancey County
Closed MSWLF	HHW	White goods	X	Incin		T&P	FIRM	PERMIT NO.: 100-03T
CDLF	Tire T&P / Collection	Tire Monofili		Industrial Landfill		DEMO	SDTF	FILE TYPE: COMPLIANCE

Date of Audit: November 15, 2005.

Date of Last Audit: September 20, 2005.

FACILITY NAME AND ADDRESS:

Yancey County Transfer Station Booneford Rd,

Bandana, N.C. 28714

FACILITY CONTACT NAME AND PHONE NUMBER:

Michelle Lawhern, Co. Manager 828-682-3971 Anthony Allen, SW Director 828-678-9180

FACILITY CONTACT ADDRESS (IF DIFFERENT):

Court House,

Burnsville, NC. 28714

AUDIT PARTICIPANTS:

Albert A. Hetzell WMS, Solid Waste Section, DENR Kris Bank, Facility Operator, Waste Manage Management Robert Blevins, County Heavy Equipment Operator, Yancey County

STATUS OF PERMIT:

Expired - Review Date September 7, 2005

PURPOSE OF AUDIT:

Comprehensive Audit

NOTICE OF VIOLATION(S) (citation and explanation): None

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$5,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. If the violation(s) noted here continue, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

STATUS OF PAST NOTED VIOLATIONS (List all noted last audit):

None

OTHER COMMENTS /SUGGESTIONS: Audit time 4:00~4:30 PM

- 1.) Trailer loading bay being cleaned at the end of the day.
- 2.) Vegetation around Transfer Station needs mowing.
- 3.) Very little metal on floor. Fuel and propane gas tanks are being separated for recycling.
- 4.) Scrap metal loading floor needs to be washed down periodically.
- 5.) The steel lip in the White goods area has a gap between it and the concrete.
- 6.) Repair work is need to building in the exit door of the truck loading area.
- 7.) The waste collection floor is in need of repair.





FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

- 8.) Wood waste is being ground periodically.
- 9.) Transfer station floor repair is needed in the near future.
- 10.) Overall operation is OK.
- 11.) Weather Cloudy, dry.

Please contact me if you have any questions or concerns regarding this audit report.

Why fee 1945 Phone: 828-296-4701.

Regional Representative/WMS

	the state of the s						
4		 			****		1 -
- 1	• •						l.
- 1				T TO 3 C 11		G 21C 137 C 3	Ĺ
	Mailed on: November 17, 2005.	hand delivery	v	US Mail		Certified No.	
	141anca on10vember 17, 20001	mana actively	Δ	Q.D. 1.1.0.1.1			L
							ł
	by						Į
	U y					· · · · · · · · · · · · · · · · · · ·	

Distribution: original signed copy to facility - signed copy to compliance officer - email or copy to supervisor

CC: Mark Poindexter, Field Operations Branch Head Brent Rockett, Western District Supervisor